

NATIONAL TRANSPORTATION SAFETY BOARD	ACCIDENT NUMBER:
RETENTION / RELEASE OF WRECKAGE RELATED TO ACCIDENT NUMBER ►	WPR24LA139

For Use In All Modal Investigations

REGISTERED OWNER (name and address)		IDENTIFICATION NUMBER	
Emerald City Aircraft Leasing Inc Port Orchard, WA 98366		N4082J	
		MAKE	
		Robinson Helicopter	
LOCATION	DATE OF ACCIDENT	MODEL	
Tumwater, WA	05/03/2024	R22 Beta	
RETAINED BY NTSB REPRESENTATIVE		TITLE	DATE
Kristyn Blocher		Air Safety Investigator	05/06/2024
The National Transportation Safety Board has ☒ has not ☐ completed its investigation of the wreckage described above. All recovered wreckage except that listed in the evidence control for (s) is hereby released.			
☒ NO PARTS RETAINED			
RELEASED BY NTSB REPRESENTATIVE		TITLE	DATE
Kristyn Blocher		Air Safety Investigator	02/25/2025
(This section may be acknowledged by a person, not the owner or owner's representative, who has knowledge of the disposition of the recovered wreckage and its parts. Such acknowledgement does not place responsibility for disposition of the wreckage upon that person.)			
I HEREBY ACKNOWLEDGE:			
☐ Receipt of the above described wreckage.			
☐ Removal of the parts, if any, listed in the evidence control form(s).			
PERSON MAKING ACKNOWLEDGEMENT		TITLE	DATE
[REDACTED]		Adjuster	3/5/25
ADDRESS		PHONE NUMBER & EMAIL	
[REDACTED]		[REDACTED]	
REMARKS:			
Note: The primary avionics console, including avionics which had been installed at the time of the accident, was discovered to have been altered without NTSB knowledge or permission, after notification of NTSB wreckage retention, but prior to wreckage recovery. The wreckage being released includes the console and avionics that the alterer placed into the wreckage prior to its recovery from the accident location.			