

WPR24LA173

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Full view of the tail rotor (Courtesy of the operator)



Photograph 2 - Close-up of tip damage (Courtesy of the operator)



Photograph 3 - Close-up of tip and trailing edge damage (Courtesy of the operator)