



Fabian Salazar
Air Safety Investigator
Western Pacific Region

Date: April 8, 2026

Subject: WPR24LA214 / Record of Conversation

Contact: [REDACTED], Owner, Allied Ag Cat, Walnut Ridge, AR

During a telephone conversation with the owner, he explained that the TPE-331 turbo-propeller engine was not a factory installation for the G-164B airplane, and the factory does not have performance charts for a G-164B airplane that is equipped with a TPE-331 turbo-propeller engine. He further explained that the TPE-331 engine was installed on the G-164B airplane in accordance with a supplemental type certificate (STC).