
WPR24LA214 (Pleasant Grove, CA) SATLOC M3 CPU Email Report

From Tatum Butler [REDACTED]
Date Wed 2/4/2026 10:30 AM
To Fabian Salazar [REDACTED]
Cc Christopher Babcock [REDACTED]

 3 attachments (10 MB)
SATLOCM3CPU.JPG; PCMCIA.JPG; 2.5inFlashDrive.JPG;

Email Report Instructions

The narrative and attachments from this email report may be used in other reports at the discretion of the IIC. This email, including attachments (if applicable), should also be placed in the public docket.

Email Report

The Vehicle Recorder Division received a SATLOC M3 CPU unit (p/n 806-1001-15A, s/n 0842-8110-0008) and PCMCIA card associated with the M3 unit. The devices arrived with minimal signs of damage (SATLOCM3CPU.JPG and PCMCIA.JPG).

The PCMCIA card was corrupted and unreadable. No folders or file structure could be recovered from the memory. No data was recovered from the device.

The internal memory from the M3 CPU was recovered from a 2.5" flash drive (2.5inFlashDrive.JPG). The flash drive contained systems data and one log file from 06/27/2000. No accident-related data was recorded by the device.

Prepared by: Tatum Butler, Recorder Specialist, NTSB RE-40



SLXg3

High Accuracy DGPS Receiver

SATLOC

PRECISION GPS APPLICATIONS

GPS DIFF
PWR / POS
MODE



Centennial

**PCMCIA SRAM
Memory Card**

SATLOC, INC.
VER. 1.10A



▼ Insert This Way

RoHS
Compliant

MASTER

SLAVE

2.5" Flash Drive

V2.5.33

1GB

SLFLD25-1GM1UI

