

WPR24LA230

INVESTIGATION PHOTOGRAPHS

March 19, 2025



Photograph 1 - N36RW at the accident site. (Courtesy of pilot)



Photograph 2 - N36RW at secured facility.



Photograph 3 - Substantial damage to left horizontal stabilizer and elevator. (Courtesy of pilot)