

WPR24LA241

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of accident helicopter in an open field (Courtesy of pilot)



Photograph 2 - View of separated tail rotor assembly and vertical & horizontal stabilizer in an open field (Courtesy of pilot)