



Eleazar Nepomuceno
Aviation Accident Investigator
Aviation Safety - Western Pacific Region

Date: September 1, 2026

Subject: WPR24LA307 IIC Correspondence

Contact: Dwight Thompson, Townsend (8U8) Airport Manager

After multiple attempts through email and phone calls, the Townsend Airport Manager did not provide a fuel quality check report from the time of the accident.