



Scott Johnson
Air Safety Investigator
Western Pacific Region

Date: 09/25/2024

Subject: 6120 Mechanical Malfunction/Failure Clarification / WPR24LA312

Contact: Raymond Dieckman

The following is a synopsis of the information provided by Mr. Dieckman in a telephone conversation.

According to the pilot there were no preimpact mechanical failures or malfunctions with the airframe or engine that would have precluded normal operation.

Total time: 33000

Make and Model: 65