

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
--------------------	---------------------------	-------------------	-----------------------------	---

N Number: N6522Z
 Tach/Hobbs: 435.0
 AFTT: 7006.7
 EngTT: 626.0
 EngTSO: 626.0
 PropTT: 2153.3
 PropTSO: 1099.7



Hangtown Aviation
 3501 Airport Rd. H34 Placerville CA, 95667
 hangtownaviation.net

Aircraft: U206G
 S/N: U20606307
 Engine: IO-550-F21B
 S/N: 1042820
 Prop: PHC-J3YF-1RF
 S/N: FP7675B
 DATE: 11/25/2023

Inspected and cleaned fuel strainer, reassembled with new packing and lock-wired. Lubed all pulleys, rod, ends and hinges.
 Inspected Camera and equipment for security per ICA. C/W Brackett air filter ICA and replaced element.

C/W AD 20-18-01(11/12/2020) per SEB 93-5 paragraphs 1.A B,C & 1.B; no defects noted. Next due 1000hrs TIS.
 C/W AD 2011-10-09 (06/17/2006) Seat rail and seat inspection per paragraph (G)1-10, next due 100hrs TIS.
 C/W AD 85-10-02 (06/20/1985) Induction airbox in accordance with paragraphs (a & b); next due 100hrs TIS.

"I certify this aircraft has been inspected in accordance with an annual inspection per FAR 43 appendix "D" and has been determined to be in an airworthy condition."

A&P

X

Date	Total Time		Time Since Last Overhaul		Engine Service and Maintenance Record
	Hours	Min	Hours	Min	
Record maintenance actions including engine part removal and installation and compliance with inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins					
Carried forward →					

N Number: N6522Z
 Tach/Hobbs: 435.0
 AFTT: 7006.7
 EngTT: 626.0
 EngTSO: 626.0
 PropTT: 2153.3
 PropTSO: 1099.7



Hangtown Aviation
 3501 Airport Rd. H34 Placerville CA, 95667
 hangtownaviation.net

Aircraft: U206G
 S/N: U20606307
 Engine: IO-550-F21B
 S/N: 1042820
 Prop: PHC-J3YF-1RF
 S/N: FP7675B
 DATE: 11/25/2023

Drained engine oil, removed and inspected oil filter, no contaminants found. Installed new CH48109-1 and 12qts phillips 100AW
 Serviced spark plugs and gaskets. Inspected fuel inlet screen and reassembled with new gasket and lock wired. Compression
 Checks 1)72 2)73 3)64 4)71 5)72 6)74 /80. Ran engine per FAR 43.15 (C)2. Operational checks satisfactory, no leaks noted at
 this time.

"I certify this engine has been inspected in accordance with an annual inspection per FAR 43 appendix "D" and has been
 determined to be in an airworthy condition."

A&P

X

N Number: N6522Z Tach/Hobbs: 469.7 AFTT: EngTT: EngTSO: PropTT: PropTSO:	Hangtown Aviation 3501 Airport Rd. H34 Placerville CA, 95667 hangtownaviation.net	Aircraft: U206G S/N: Engine: S/N: Prop: S/N: DATE: 01/29/2024
Drained oil thru Continental screen, Removed oil Filter. Installed new oil filter AA48109. serviced with 12 qts Aeroshell w100. Inspected filter trace amounts of metal found. recheck at 25 hrs. Ran aircraft no leaks noted. Replaced #4 EGT probe with serviceable JPI Probe.		
A&P	X	

02/14/2024
 Tach: 484.2

Oil & Filter change. Trace amounts
 of metal found but less than last oil
 change. Recommend rechecking in 25 hrs
 TIS. Installed new AA48109 & 12 qts Aeroshell
 100W. Ran engine, no leaks noted.

Date	Total Time		Time Since Last Overhaul		Engine Service and Maintenance Record Record maintenance actions including engine part removal and installation and compliance with inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins
	Hours	Min	Hours	Min	

N Number:	N6522Z	 Hangtown Aviation 3501 Airport Rd. H34 Placerville CA, 95667 hangtownaviation.net	Aircraft:	U206G
Tach/Hobbs:	683.3		S/N:	
AFTT:			Engine:	
EngTT:			S/N:	
EngTSO:			Prop:	
PropTT:			S/N:	
PropTSO:		DATE:	08/29/2024	

Drained Engine oil, removed oil filter. inspected filter no contaminants found. installed new aa48108 oilfilter, serviced with 12 qts Aeroshell W100. ran engine no leaks noted. *Sample Taken*

A&P		X
-----	--	---

YEAR
20____
DATE

RECORDING
TACH
TIME

TODAY'S
FLIGHT

TOTAL
TIME IN
SERVICE

Description of Inspections, Tests, Repairs and Alterations
Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

N Number: N6522Z
Tach/Hobbs: 3045.0
AFTT: 6380.7
EngTT: 1527.3
EngTSO: 1527.3
PropTT: 1527.3
PropTSO: 473.7



Hangtown Aviation

3501 Airport Rd. H34 Placerville CA, 95667
hangtownaviation.net

Aircraft: U206G
S/N: U20606307
Engine: IO-550-F21B
S/N: 1004458
Prop: PHC-J3YF-1RF
S/N: FP7675B
DATE: 07/06/2022

Removed IO-550-F(21) SN 1004458 engine from N6522Z and installed IO-550F(21) SN 1042820 rebuilt by Continental aerospace technologies, Inc per Cessna 206 MM. See work order 601100. New engine Total time 0.0 Hrs @ AFTT; 6380.7
Fabricate patch on LH side cowling. Patch made in accordance with AC43.13
Replaced mixture control PN MC9862066-1

Repaired engine induction airbox, reinstalled alternate air valve after repairs by Loree Air Inc. See work order. Installed new lever MC0750111-19 and replaced one bearing 1250309-1.

A&P

X