



Eleazar Nepomuceno
Aviation Accident Investigator
Aviation Safety - Western Pacific Region

Date: January 15, 2025

Subject: WPR25LA030, Summary of conversation

Contact: Pilot, John Rocha

During a conversation with the pilot, he reported that the last time the engine was overhauled in October 1997, according to the engine logbook entry. Most recently, the pilot mentioned that the last engine log entry took place on September 16, 2023, for an annual inspection. The pilot added that prior to the accident flight, he was going to request a local maintenance shop to troubleshoot and trace an oil leak that gave him concerns.