

WPR25LA034

INVESTIGATION PHOTOGRAPHS



Photograph 1 - N4361R at the accident site. (Courtesy of the operator)



Photograph 2 - Top view (Courtesy of the operator)



Photograph 3 - Rear view (Courtesy of the operator)



Photograph 4 - Contents of the sling load (Courtesy of the operator)