

WPR25LA093

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the damaged main rotor blade. (Courtesy of the pilot)



Photograph 2 - View of the main rotor blade. (Courtesy of the pilot)



Photograph 3 - View of the left side tailboom. (Courtesy of the pilot)