

Zane Brown

From: Ray Shipway [REDACTED]
Sent: Wednesday, February 26, 2025 3:30 PM
To: Zane Brown
Subject: Re: Rotax seizure

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

The Radiator cap #8
Sent from my iPhone

On Feb 26, 2025, at 12:33, Zane Brown [REDACTED] wrote:

Mr. Shipway,
Thank you for the 6120 and photos.
I have a few questions for you,
What brand and type of oil was the engine serviced with?
In the 6120.1 and our telephone conversation, you noted that the expansion cap was missing, and later, in the 6120.1, you wrote that the radiator cap was removed. I want to confirm which cap you are referring to. Referring to Figure 1, is the missing cap item #8 or item #12?




Figure 1

- | | |
|---------------------------------------|---|
| 1 Crankcase | 2 Cylinder |
| 3 Cylinder head | 4 Water pump |
| 5 Radiator | 6 Hose from radiator to water pump |
| 7 Hose from cylinder head to radiator | 8 Radiator screw cap, with excess pressure valve and return valve |
| 9 Temperature gauge for cooling water | 10 Overflow hose |
| 11 Overflow bottle | 12 Bottle venting |
| 13 Expansion tank | 14 Cylinder head venting hose |

Thank you for your assistance,



Zane Brown

Aviation Accident Investigator
Coeur d'Alene, Idaho

Office: [REDACTED]

Mobile: [REDACTED]

Email: [REDACTED]

Web: www.nts.gov

Response Operations Center (24/7): 1-844-373-9922
Work Hours: Monday-Thursday, 0700-1600 Pacific Time

From: Ray Shipway [REDACTED]
Sent: Wednesday, February 26, 2025 9:26 AM
To: Zane Brown [REDACTED]
Subject: Rotax seizure

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.





Sent from my iPhone