



Kristyn Blocher
Air Safety Investigator
AS-WPR

Date: June 16, 2025

Subject: Wreckage Recovery, N71450

Contact: Recovery Personnel with D Zone Skydiving

The following is a summary of events and telephone communications during the postaccident recovery of N71450:

At the request of NTSB investigator Blocher, recovery personnel were asked to drain and measure all fuel recovered from the airplane's fuel tanks. No fuel drained from the left or right wing fuel tanks. Visual inspection of both tanks revealed no fuel in either tank. The vegetation and surrounding area were inspected for signs of leaked fuel; none was found. At Blocher's request, they visually inspected the gascolator and found it to be securely attached. They drained trace amounts of fuel from that location.