

WPR25LA203

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View tail damage (Courtesy of pilot)



Photograph 2 - View of main rotor damage (Courtesy of Pilot)