


WPR25LA304

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Substantial damage to firewall. (Courtesy of the airport manager)



Photograph 2 - Substantial damage to the left aileron. (Courtesy of airport manager)