

WPR26LA056

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Damage to tailboom (Courtesy of San Bernardino County Sheriff)



Photograph 2 - Damage to tail rotor blades (Courtesy of San Bernardino County Sheriff)



Photograph 3 - Throttle cable without securing nut (Courtesy of Owner)



Photograph 4 - Throttle assembly (Courtesy of Owner)