



Grant Mills  
Air Safety Investigator  
Western Pacific Region

**Date:** January 6, 2026

**Subject:** WPR26LA071, Memorandum for Record

**Contact:** [REDACTED] Air Transport

The following is a synopsis of the information provided by [REDACTED] in a conversation.

When they arrived at the accident site location, they observed the accident airplane, N272HM, a Cirrus, SR22 on the side of a hill. A fracture was observed on the aft section of the fuselage. Although efforts were made to recover the airplane intact, due to the damage sustained during impact, the aft portion of the fuselage and the empennage separated from the fuselage.