

WPR26LA102

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of aircraft from right rear (Courtesy of Pilot)



Photograph 2 - View of aircraft from left rear (Courtesy of Pilot)



Photograph 3 - View showing tire skid marks on ramp (Courtesy of Pilot)



Photograph 4 - Right seat on rails, slid full forward (Courtesy of FAA)



Photograph 5 - Right seat on seat rails (Courtesy of FAA)



Photograph 6 - Right seat rail forward stop mounting hardware (Club maintenance director)