

Grant Mills
Air Safety Investigator
Western Pacific Region

Date: July 10, 2026

Subject: WPR26LA241, Memorandum for Record

Contact: [REDACTED] Mechanic

The following is a synopsis of the information provided by [REDACTED] in a text message exchange.

[REDACTED] reported that he traveled from Bend, Oregon to Port Angeles, Washington to examine and repair a Cessna 180H, N3404Y. The examination revealed that damage to the airplane was limited to the left aileron, one wing rib, and the left elevator. All of which were repaired in Port Angeles. The mechanic examined the gear box, brakes, landing gear, and flight controls. A test flight was conducted at the airport in Port Angeles, and the airplane was subsequently flown to Bend, Oregon. The examination and flights revealed that there were no mechanical malfunctions or failures with the airplane that would have precluded normal operation.