



Photo 1: Broken Tree Top



Photo 2: Broken Tree Top



Photo 3: Initial Tree Impact



Photo 4: Broken Tree Branch



Photo 5: Sliced Tree Branch



Photo 6: Fractured Rocker Cover



Photo 7: Opened Cowling Access Panel



Photo 8: Accident Airplane Post-Fire