



Figure 1: Aerial view of the wreckage and East Wind Lake



Figure 2: View of the left side of the airplane and floats



Figure 3: Forward view of the wreckage, facing East Wind Lake



Figure 4: View of the tail and aft portion of the airplane



Figure 5: The right wing and tail



Figure 6: Measurement of the jackscrew