



Photo 1 – View of fuselage (courtesy of the operator)



Photo 2 – View of fuselage and tailboom (courtesy of the operator)



Photo 3 – View of tailboom and tail rotor assembly (courtesy of the operator)



Photo 4 – Aerial view of accident site (courtesy of the operator)



Photo 5 – Aerial view of accident site (courtesy of the operator)




Photo 6 – View of cabin (courtesy of the operator)



Photo 7 – View of cockpit (courtesy of the operator)



Photo 8 – View of metal heater (courtesy of the operator)



Photo 9 – View of cabin



Photo 10 – View of cockpit



Photo 11 – View of pilot's seat from left side



Photo 12 – View of pilot's seat from front side



ERA
Front Right Seat

Photo 13 – View of pilot's seat from right side



Photo 14 – View of radar altimeter and attitude indicator