



Figure 1 (left side image): The left and right images were taken by the witness. The left image shows the airplane with flaps extended during the taxi prior to takeoff and right image shows the airplane with its flaps retracted during its takeoff run.



Figure 1 (right side image): The left and right images were taken by the witness. The left image shows the airplane with flaps extended during the taxi prior to takeoff and right image shows the airplane with its flaps retracted during its takeoff run.