



Photo 1 – Accident airplane at accident site.



Photo 2 – Tailwheel folded underneath the empennage of the accident airplane at the accident site.



Photo 3 – Trench in airstrip's landing surface.