

Radar Study – Attachment 1

Radar Graphics

AIR TRAFFIC CONTROL

ANC17FA004



Figure 1 - Radar graphic depicting the accident aircraft departing Lake Hood.



Figure 2 - Radar graphic showing the entire flight as it traveled west along the coastline.




Figure 3 - Radar graphic showing the accident aircraft turning northwest.




Figure 4 - Radar graphic showing the final portion of the flight to the accident location.