



Photo 1 – Accident airplane at wreckage layout.




Photo 2 – Displaced crankshaft oil seal.



Photo 3 – Engine breather tube.