



Photo 1 – Accident airplane near accident site during the rescue.



Photo 2 – Accident airplane near accident site.



Photo 3 – Accident airplane near accident site during the rescue and recovery.



Photo 4 – Accident airplane being towed to Trident Basin Seaplane Base during the recovery.



Photo 5 – Accident airplane at Trident Basin Seaplane Base dock, prior to removal of the wreckage from the water.



Photo 6 – Accident airplane's separated float struts.



Photo 7 – Accident airplane's right rear float strut and severed hydraulic lines.



Photo 8 – Accident airplane's right middle float strut and severed hydraulic line.