



Photo 1 –N1203A PA-18 wreckage on June 12, 2018 in the Katlian River.



Photo 2 - Initial impact river bottom depression with debris and cut tree trunk sections.



Photo 3 - Left wing.



Photo 4 - Right wing with missing fuel tank cap.



Photo 5 - Rear view of wreckage exhibiting right twist and displacement in aft fuselage.



Photo 6 - Front seat (pilot's) shoulder harness inertia reel mounted on cut tube.



Photo 7 - Rear seat (passenger's) lap belt buckle exhibiting deformation.



Photo 8 - Rear seat shoulder harness connectors.



Photo 9 - Propeller and engine during detailed examination.