



Photo 1 – View of the left side of the airplane on the runway.



Photo 2 – View of the right side of the airplane on the runway.



Photo 3 – View of the Garmin G1000 avionics suite.



Photo 4 – View of the cockpit.



Photo 5 – View of the landing gear selector.




Photo 6 – View of the fractured right engine mount (courtesy of Bering Air).