



Photo 1 – View of the airplane on the grass (courtesy of the FAA).



Photo 2 – View of the fractured left main landing gear assembly (courtesy of the FAA).



Photo 3 – View of the tire from the fractured left main landing gear assembly (courtesy of the FAA).