

20180320 N716JP Damage (6/18)



Photo 1 – Close View of Left Wing and Aileron



Photo 2 – Satellite Image of Ice Airstrip Taken 3/21/18



Photo 3 – Overall View of Left Wing Damage