



Photo 1 – Aerial view of the accident airplane at the accident scene.



Photo 2 – Accident airplane at accident scene.



Photo 3 – Anti-spin chute activation lanyard.



Photo 4 – Opened connector hook for anti-spin chute.