



Photo 1 – Photo of light sport airplane at accident site, before wreckage recovery. (Courtesy of FAA)



Photo 2 – Photo of severed engine taken at accident scene. (Courtesy of FAA)



Photo 3 – Photo of main fuselage/cockpit area in tree and accident site. (Courtesy of FAA)



Photo 4 – Photo of wing/sail assembly in tree and accident site. (Courtesy of FAA)