



Photo 1 – N8070Z Cessna 206 wreckage, bottom of airplane (courtesy of airplane owner)



Photo 2 - N8070Z Cessna 206 wreckage, laying on right side (courtesy of airplane owner)




Photo 3 - Rear view of N8070Z wreckage (courtesy of airplane owner)



Photo 4 - Willow Airport and N8070Z wreckage