



Photo 1 – Exterior damaged area of accident airplane.



Photo 2 – Aft fuselage skin damage to accident airplane.



Photo 3 – Damaged bulkhead on accident airplane.