



Photo 1 – Aerial view of accident airplane at accident site.



Photo 2 – Left side of accident airplane after recovery from the ocean waters.



Photo 3 – Right side of accident airplane after recovery from the ocean waters.



Photo 4 – Fuselage of accident airplane.



Photo 5 – Cockpit of accident airplane.



Photo 6 – Left float attach forward flying wire compression signature.



Photo 7 – Left float attach rear flying wire compression signature.