



Photo 1 – Loose B-Nut Found on Oil Cooler, Looking Up (FAA Photo)



Photo 2 - Loose B-Nut Looking from the Side (FAA Photo)



Photo 3 - Loose B-Nut Looking Down through Engine (FAA Photo)



Photo 4 - Airplane Wreckage after Recovery (FAA Photo)