



Photo 1 – Rear view of accident airplane with wings removed (Photo courtesy of the NTSB)



Photo 2 – View of corroded aft lower fuselage tube (Photo courtesy of the NTSB)



Photo 3 – View of corroded tailwheel mount cross-tube (Photo courtesy of the NTSB)



Photo 4 – View of corroded tailwheel attach bolt (Photo courtesy of the NTSB)



Photo 5 – Additional view of corroded tailwheel attach bolt (Photo courtesy of the NTSB)



Photo 6 - View of damaged rudder (Photo courtesy of the FAA)