



Photo 1 –N9448B Cessna 208 wreckage at the accident site at Bethel Airport. (Source: Grant Aviation)



Photo 2 - Wreckage laying on the right fuselage. (Source: Grant Aviation)



Photo 3 - Right wing exhibiting upward deformation and left wing detached and resting on the right wing. (Source: Grant Aviation)



Photo 4. - Empennage. (Source: Grant Aviation)



Photo 5 - Propeller, engine and front fuselage exhibiting significant impact deformation. (Source: Grant Aviation)



Photo 6 - Bottom fuselage exhibiting extensive fire damage. (Source: Grant Aviation)



Photo 7 - Cabin floor and interior exhibiting significant fire damage. (Source: Grant Aviation)