



**Photo 1 – Front view of damaged airplane with engine displaced (Photo courtesy of the local law enforcement)**



**Photo 2 – Rear view of damaged airplane with engine displaced (Photo courtesy of the local law enforcement)**