



Photo 1 – Rear view of airplane in the ditch (Photo courtesy of the operator)



Photo 2 – View from tip of left wing (Photo courtesy of the operator)



Photo 3 – Rear view of damaged left aileron (Photo courtesy of the operator)



Photo 4 – Front view of airplane with separated gear case (Photo courtesy of the operator)