



MOKULELE AIRLINES
KAILUA - KONA, HI, USA, 96740

208B - CARAVAN (MSG) N879MA S/N: 208B-5019

Work Order #: N879MA14198

Date	A/C HRS	A/C AFL	ENG 1 HRS	ENG 1 ENC	PROP 1 HRS					
16-Jul-2019	8697.5	16850								

No.	Task No./Position	Description
1	053401	UPDATE G1000 NAV DATA Update Note: C/W G1000 NAV DATABASE UPDATE REF GARMIN G1000 MM
2	058901	MOKULELE ONE MONTH SPECIAL INSPECTION Update Note: C/W MOKULELE ONE MONTH SPECIAL INSPECTION REF CHAPTER 3 MOKULELE SPECIAL INSPECTIONS.
3	05MX-01	PERFORM DAILY CHECK Update Note: C/W DAILY CHECK REF MX-1
4	05MX-03	PERFORM YEARLY OPERATORS REPORT TBO EXTENSION OPTION B Update Note: C/W YEARLY OPERATORS REPORT TBO EXTENSION OPTION B TBO EXTENSION GRANTED TO 6000HR REF TBO OPTION B EVALUATION LETTER DATED MARCH 27,2019 REF STP 4385 AND CRM CASE PWC-118421-Q8K0.
5	240501	BATTERY Removed 7638-44 S/N# G03020848 Reason Removed CO-CONVENIENCE Installed 7638-44 S/N# 03021437 Installed Part Times Update Note: INSTALLED SERVICEABLE BATTERY REF AMM 24-33-00.
6	B243201	FUNCTIONAL CHECK BATTERY GILL FLOODED LEAD-ACID BATTERY (CAPACITY CHECK) Update Note: C/W FUNCTIONAL/CAPACITY CHECK BATTERY REF AMM 24-34-00
7	CAL-05-02	TIME LIMITS/MAINTENANCE CHECKS - NEW C100490-1 OIL COOLER CHECK VALVE (CHECK VALVE ASSEMBLY REPAIR) RESTORATION INTERVAL IMPLEMENTATION GRACE PERIOD, SERVICE LETTER Method Of Compliance: COMPLIED WITH Update Note: REMOVED AND REPLACED OIL COOLER CHECK VALVE WITH REPAIR KIT 54561-2 REF SIL CAL-79-01. AIRCRAFT HOBBS WHEN ACCOMPLISHED 8697.5 NEXT DUE IN 1800HRS AT 10497.5.
8	N879MA-190429-1	LH MLG TIRE WORN TO LIMITS Update Note: R/R L/H MLG TIRE ASSY REF AMM 32-40-00.
9	N879MA-190430-1	REMOVED BATTERY TO FACILITATE OTHER MAINTENANCE ON N887MA Update Note: INSTALLED SERVICEABLE BATTERY REF 208B AMM 24-33-00. PN#7638-44 SN#G03021437.
10	N879MA-190519-1	REMOVED TOP R/H MLG FAIRING TO FACILITATE MX ON 856 Update Note: REINSTALLED SERVICEABLE R/H MLG FITTING REF AMM 32-10-00
11	N879MA-190704-1	REMOVED OVER SPEED SENSOR PN#251500-0187 SN#266295 TO ACCOMMODATE AIRCRAFT N808MA. REPLACEMENT OF PART WILL REQUIRE PITOT STATIC LEAK CHECK AND OPS CHECK. Update Note: INSTALLED SERVICEABLE AIRSPEED SENSOR AND PERFORMED PITOT/STATIC LEAK CHECK REF AMM 34-11-01. PERFORMED LOW SPEED AWARENESS SYSTEM FUNCTIONAL CHECK REF AMM 34-11-01.
12	N879MA-190714-1	REMOVED EXCITER BOX PN: CH92106-1 SN: 15035982 TO FACILITATE N847MA.. NO OTHERS IN STOCK.. WILL NOTIFY STOCKROOM TO GET MORE 7/14/19 Update Note: INSTALLED SERVICEABLE EXCITER BOX PN#CH92106-1 SN#132033 REF AMM 74-10-00.
13	N879MA-190716-1	PROPELLER CONTROL LEVER NEEDS ADJUSTED (FEATHER STOP NOT FULLY REACHED) Update Note: ADJUSTED PROPELLER CONTROL LEVER REF C208B 76-12-05

I CERTIFY THAT THIS AIRCRAFT/ENGINE/PROPELLER WAS REPAIRED (IN ACCORDANCE WITH CURRENT FAA REGULATIONS) AND/OR INSPECTED IN ACCORDANCE WITH MOKULELE FLIGHT SERVICE AAIP AS REQUIRED BY FAR135.419 AND IS APPROVED FOR RETURN TO SERVICE.

Work Performed By:

Certificate #:

A&P



MOKULELE AIRLINES
[REDACTED]
KAILUA - KONA, HI, USA, 96740

HC-B3TN-3AF/T10890CNK-2 HC-B3TN-3AF S/N: BUA33219

On Aircraft Reg : N879MA Serial : 208B-5019

Work Order #: N879MA14198

Date	A/C HRS	A/C AFL	ENG 1 HRS	ENG 1 ENC	PROP 1 HRS					
16-Jul-2019	8697.5	16850			7540.5					

No.	Task No. / Position	Description
-----	---------------------	-------------

1	614010	NO. 1 PROPELLER - INSPECT PROPELLER
---	--------	-------------------------------------

Update Note: C/W PROPELLER INSPECTION REF HARTZELL MM.

I CERTIFY THAT THIS AIRCRAFT/ENGINE/PROPELLER WAS REPAIRED (IN ACCORDANCE WITH CURRENT FAA REGULATIONS) AND/OR INSPECTED IN ACCORDANCE WITH MOKULELE FLIGHT SERVICE AAIP AS REQUIRED BY FAR135.419 AND IS APPROVED FOR RETURN TO SERVICE.

Work Performed By:



Certificate #:

ASP [REDACTED]



MOKULELE AIRLINES
KAILUA - KONA, HI, USA, 96740

208B CARAVAN N879MA S/N: 208B-5019

Work Order #: N879MA15159

Date	A/C HRS	A/C AFL	ENG 1 HRS	ENG 1 ENC	PROP 1 HRS				
07-Aug-2019	8763.8	16988							

No.	Task No./Position	Description
1	05MX-01	PERFORM DAILY CHECK

Update Note: PERFORMED DAILY AIRCRAFT INSPECTION REF FORM MX 1

I CERTIFY THAT THIS AIRCRAFT/ENGINE/PROPELLER WAS REPAIRED (IN ACCORDANCE WITH CURRENT FAA REGULATIONS) AND/OR INSPECTED IN ACCORDANCE WITH MOKULELE FLIGHT SERVICE AAP AS REQUIRED BY FAR135.419 AND IS APPROVED FOR RETURN TO SERVICE.

Work Performed By:

Certificate #:

A+P



MOKULELE AIRLINES
KAILUA - KONA, HI, USA, 96740

PT6A-140 3076226-01 BS1294 S/N: PCE-VA0408

On Aircraft Reg : N879MA Serial : 208B-5019

Work Order #: N879MA15159

Date	A/C HRS	A/C AFL	ENG 1 HRS	ENG 1 ENC	PROP 1 HRS				
07-Aug-2019	8763.8	16988	3660.5	7115					

No.	Task No./Position	Description
1	710050	NO. 1 ENGINE - COMPRESSOR/TURBINE DESALINATION RINSE

Update Note: PERFORMED COMPRESSOR/ TURBINE BLADE RINSE REF P8WC EMM 71-00-00

I CERTIFY THAT THIS AIRCRAFT/ENGINE/PROPELLER WAS REPAIRED (IN ACCORDANCE WITH CURRENT FAA REGULATIONS) AND/OR INSPECTED IN ACCORDANCE WITH MOKULELE FLIGHT SERVICE AAP AS REQUIRED BY FAR135.419 AND IS APPROVED FOR RETURN TO SERVICE.

Work Performed By:

Certificate #:

A+P



MOKULELE AIRLINES
KAILUA - KONA, HI, USA, 96740

HC-B3TN-3AF/T10890CNK-2 HC-B3TN-3AF S/N: BUA33219

On Aircraft Reg : N879MA Serial : 208B-5019

Work Order #: N879MA15159

Date	A/C HRS	A/C AFL	ENG 1 HRS	ENG 1 ENC	PROP 1 HRS				
07-Aug-2019	8763.8	16988			7506.9				

No.	Task No./Position	Description
1	610040	NO. 1 PROPELLER - PROPELLER 100 HOUR INSPECTION
		Update Note: COMPLETED NO. 1 PROPELLER 100 HOUR INSPECTION REF CESSNA AMM 61-00-00
2	615010	NO. 1 PROPELLER - INSPECTION DE-ICE SYSTEM
		Update Note: N/A. SYSTEM DEACTIVATED
3	617010	NO. 1 PROPELLER - INSPECTION ANTI-ICE SYSTEM
		Update Note: N/A. SYSTEM DEACTIVATED

I CERTIFY THAT THIS AIRCRAFT/ENGINE/PROPELLER WAS REPAIRED (IN ACCORDANCE WITH CURRENT FAA REGULATIONS) AND/OR INSPECTED IN ACCORDANCE WITH MOKULELE FLIGHT SERVICE AAP AS REQUIRED BY FAR135.419 AND IS APPROVED FOR RETURN TO SERVICE.

Work Performed By:

Certificate #:

A+P

CHECK CURRENT DUE LIST FOR DUE TIME CHANGES

Operator: **MOKULELE AIRLINES** Work Card No.: **61.100**
 Serial No.: **BUA33219** Model: **HC-B3TN-3AF/T10890CNK-2**
 Part: **HC-B3TN-3AF** Workorder No.: **N879MA15159**
 Eng. Serial **208B-5019** Part:

Date of Work	Time	Time	Time	Time	Time	Time
30-APR-2020	8784.4		7627.5			
07-AUG-19	8763.80	16988				

I CERTIFY THAT THIS AIRCRAFT/ENGINE/PROPELLER WAS REPAIRED (IN ACCORDANCE WITH CURRENT FAA REGULATIONS) AND/OR INSPECTED IN ACCORDANCE WITH MOKULELE FLIGHT SERVICE A&P AS REQUIRED BY FAR135.419 AND IS APPROVED FOR RETURN TO SERVICE.

TECHNICIAN SIGNATURE:  KIND OF CERTIFICATE & NO.: **A&P** 

LABOR-HRS
 165.115

>617010

NO. 1 PROPELLER - INSPECTION ANTI-ICE SYSTEM

REMARKS: N/A. SYSTEM DEACTIVATED

N/A. SYSTEM DEACTIVATED

N/A. SYSTEM DEACTIVATED

GENERIC CUSTOM

CESSNA AIRCRAFT CO. THE GOODS AND SERVICES OF CAMP SYSTEMS INTERNATIONAL, INC. ARE NOT SPONSORED, ENDORSED, SOLD OR PROMOTED BY CESSNA AIRCRAFT CO., AND CESSNA AIRCRAFT CO. MAKES NO REPRESENTATION REGARDING THE QUALITY OF THE GOODS OR SERVICES PROVIDED BY CAMP SYSTEMS INTERNATIONAL, INC.

08-AUG-2019

WID: 37909652-1

Return completed copy via email to m

> INDICATES DUE ITEMS

© CAMP SYSTEMS

Total Pages = , Initial **1 of 2**

CHECK CURRENT DUE LIST FOR DUE TIME CHANGES

Operator: **MOKULELE AIRLINES**

Work Card No.: **61.050**

Serial No.: **8UA33219**

Model: **HC-B3TN-3AF/T10890CNK-2**

Part: **HC-B3TN-3AF**

Workorder No.: **N879MA15159**

Eng. Serial **2088-5019** Part:

DATE	TIME	AVC HRS	PROG HRS
30-APR-2020	8784.4	7627.5	
07-AUG-19	8763.80	16988	

I CERTIFY THAT THIS AIRCRAFT/ENGINE/PROPELLER WAS REPAIRED (IN ACCORDANCE WITH CURRENT FAA REGULATIONS) AND/OR INSPECTED IN ACCORDANCE WITH MOKULELE FLIGHT SERVICE AAP AS REQUIRED BY FAR135.419 AND IS APPROVED FOR RETURN TO SERVICE.

TECHNICIAN SIGNATURE

[ANTHONY CONTI]

KIND OF CERTIFICATE & NO.: A&P

>615010

NO. 1 PROPELLER - INSPECTION DE-ICE SYSTEM

REMARKS: N/A. SYSTEM DEACTIVATED

N/A. SYSTEM DEACTIVATED

N/A. SYSTEM DEACTIVATED

GENERIC CUSTOM

CESSNA AIRCRAFT CO. THE GOODS AND SERVICES OF CAMP SYSTEMS INTERNATIONAL, INC. ARE NOT SPONSORED, ENDORSED, SOLD OR PROMOTED BY CESSNA AIRCRAFT CO., AND CESSNA AIRCRAFT CO. MAKES NO REPRESENTATION REGARDING THE QUALITY OF THE GOODS OR SERVICES PROVIDED BY CAMP SYSTEMS INTERNATIONAL, INC.

08-AUG-2019

© CAMP SYSTEMS

Total Pages = _____, Initial **1** of **2**

WID: 37909651-1

Return completed copy via email to [REDACTED]

> INDICATES DUE ITEMS



CHECK CURRENT DUE LIST FOR DUE TIME CHANGES

Operator: MOKULELE AIRLINES		Work Card No.: 610040	
Serial No.: BUA33219	Model: HC-B3TN-3AF/T10890CNK-2	Workorder No.: N879MA15159	
Part: HC-B3TN-3AF	Part:		
Eng. Serial 2088-5019	Part:		

Date (DD/MM)	Time (HRS)	Time (HRS)	Time (HRS)	Time (HRS)	Time (HRS)	Time (HRS)
30-APR-2020	8784.4		7627.5			
07-AUG-19	8763.80	16988				

I CERTIFY THAT THIS AIRCRAFT/ENGINE/PROPELLER WAS REPAIRED (IN ACCORDANCE WITH CURRENT FAA REGULATIONS) AND/OR INSPECTED IN ACCORDANCE WITH MOKULELE FLIGHT SERVICE AAIP AS REQUIRED BY FAR135.419 AND IS APPROVED FOR RETURN TO SERVICE.

TECHNICIAN SIGNATURE: [REDACTED]

KIND OF CERTIFICATE & NO.: **A&P** [REDACTED]

>610040

NO. 1 PROPELLER - PROPELLER 100 HOUR INSPECTION

REMARKS: COMPLETED 100 HOUR INSPECTION REF CESSNA AMM 61-00-00 AND HARTZELL PROPELLER MM 61-10-00.
COMPLETED 100 HOUR INSPECTION REF CESSNA AMM 61-00-00 AND HARTZELL PROPELLER MM 61-10-00.
COMPLETED 100 HOUR INSPECTION REF CESSNA AMM 61-00-00 AND HARTZELL PROPELLER MM 61-10-00.

CESSNA AIRCRAFT CO. THE GOODS AND SERVICES OF CAMP SYSTEMS INTERNATIONAL, INC. ARE NOT SPONSORED, ENDORSED, SOLD OR PROMOTED BY CESSNA AIRCRAFT CO., AND CESSNA AIRCRAFT CO. MAKES NO REPRESENTATION REGARDING THE QUALITY OF THE GOODS OR SERVICES PROVIDED BY CAMP SYSTEMS INTERNATIONAL, INC.

08-AUG-2019

WID: 37909650-1

Return completed copy via email to [REDACTED] m

> INDICATES DUE ITEMS

© CAMP SYSTEMS

Total Pages = _____, Initial **1** of **1**




CHECK CURRENT DUE LIST FOR DUE TIME CHANGES

Operator: MOKULELE AIRLINES		Work Card No.: 05MX-01	
Serial No.: 208B-5019		Model: 208B CARAVAN	
Reg No.: N879MA		Workorder No.: N879MA15159	
Due At			
11-AUG-2019			
Accomplished			
07-AUG-19			
8763.80			
16988			

I CERTIFY THAT THIS AIRCRAFT/ENGINE/PROPELLER WAS REPAIRED (IN ACCORDANCE WITH CURRENT FAA REGULATIONS) AND/OR INSPECTED IN ACCORDANCE WITH MOKULELE FLIGHT SERVICE A&P AS REQUIRED BY FAR135.419 AND IS APPROVED FOR RETURN TO SERVICE.

TECHNICIAN SIGNATURE:  KIND OF CERTIFICATE & NO.: **A&P** 


FOR REPAIR
ITEMS TO BE

>05MX-01

PERFORM DAILY CHECK

REMARKS: PERFORMED DAILY AIRCRAFT INSPECTION REF FORM MX01PERFORMED DAILY AIRCRAFT INSPECTION REF FORM MX01PERFORMED DAILY AIRCRAFT INSPECTION REF FORM MX01

CESSNA AIRCRAFT CO. THE GOODS AND SERVICES OF CAMP SYSTEMS INTERNATIONAL, INC. ARE NOT SPONSORED, ENDORSED, SOLD OR PROMOTED BY CESSNA AIRCRAFT CO., AND CESSNA AIRCRAFT CO. MAKES NO REPRESENTATION REGARDING THE QUALITY OF THE GOODS OR SERVICES PROVIDED BY CAMP SYSTEMS INTERNATIONAL, INC.

08-AUG-2019

© CAMP SYSTEMS

Total Pages = _____, Initial **1** of **1**

WID: 37909649-1

Return completed copy via email to @m

> INDICATES DUE ITEMS