



**Photo 1 – Accident airplane after recovery.**



**Photo 2 – Landing gear with separated landing gear fitting attached.**



**Photo 3 – Fuselage where landing gear fitting separated.**



**Photo 4 – Separated landing gear fitting.**