



**Photo 1 – N7071B Piper PA-18 at the accident scene exhibiting substantial damage to the fuselage and right wing.
(Photograph courtesy of the owner.)**



Photo 2 - Wreckage with the wings removed before the engine examination.