



Photo 1 – View of accident airplane (Photo courtesy of the mechanic)



Photo 2 – View of damaged fuselage fitting (Photo courtesy of the mechanic)




Photo 3 – View of damaged engine mount (Photo courtesy of the FAA)