



Photo 1 – View of main rotor blade damage (Photo courtesy of the operator)



Photo 2 – Additional view of main rotor blade damage (Photo courtesy of the operator)