



Photo 1 – View of accident airplane in ditch (Photo courtesy of the Alaska State Troopers)



Photo 2 – View of damaged right-wing lift strut (Photo courtesy of the Alaska State Troopers)