



Photo 1 – N3068A Cessna 170 inverted at the accident site. (Photograph courtesy of owner.)



Photo 2 - Right wing damage. (Photograph courtesy of the owner.)