



Photo 1 – Aerial view of wreckage site taken 11/30/19.



Photo 2 - View of main wreckage site, looking downhill. (Photo provided by AMRG)




Photo 3 – View of main wreckage site, looking uphill. (Photo provided by AMRG)



Photo 4 - View of main wreckage site, looking to the southeast. (Photo provided by AMRG)



Photo 5 - View of #1 engine at accident site.



Photo 6 - View of #2 engine at accident site.




Photo 7 - ADS-B track data showing departure point (Anchorage) intended destination (Seward).




Photo 8 - ADS-B track data showing closer view and accident site.